

REMEDIAL ACTIONS FOR GRADE LEVEL CROSSINGS

Crossing ID	County Road	Remedial Measures	Cost	Status
806956	Oxford Road 29	Improve the roadway surface conditions on the eastbound approach	Low (\$500)	Complete
		Install 30 km/h 'Speed Advisory Tab' signs below the existing Railway Crossing Ahead signs and remove the 'BUMP AHEAD' signs	Low (\$500)	Complete
RX815776	Oxford Road 22	Ensure the trees that have the potential to obstruct visibility on the southwest corner are trimmed on a regular basis	Low (\$500)	Complete
		Install 30 km/h 'Speed Advisory Tab' signs below the existing Railway Crossing Ahead signs and remove the 'BUMP' and 'BUMP AHEAD' signs	Low (\$500)	Complete
375067	Oxford Road 6	Install 40 km/h 'Speed Advisory Tab' signs below the existing Railway Crossing Ahead signs and remove the 'BUMP' and 'BUMP AHEAD' signs	Low (\$500)	Complete
895087	Oxford Road 3	Prohibit on-street parking on the southeast corner of the crossing between Railway Street and the railway corridor	Low (\$500)	Outstanding
		Install 20 km/h 'Speed Advisory Tab' signs below the existing Railway Crossing Ahead signs and remove the 'BUMP' and 'BUMP AHEAD' signs	Low (\$500)	Complete
815006	Oxford Road 22	Install 30 km/h Advisory Speed Tab signs on the same post as the RAILWAY CROSSING AHEAD signs	Low (\$500)	Complete

59247	Oxford Road 59	Remove commercial signs to provide clear visibility of the crossing warning system throughout the northbound stopping sight distance	Low to medium (\$500 to \$5,000)	Outstanding
434838	Oxford Road 11	Install a Prepare to Stop at Railway Crossing sign on the northbound approach	The approximate cost for the installation of a Prepare to Stop at Railway Crossing with flashing beacons is \$60,000.	Additional review completed, determined sign was not warranted
9293	Oxford Road 9	Install 30 km/h 'Speed Advisory Tab' signs below the existing Railway Crossing Ahead signs, remove the 'BUMP' signs and the custom signs indicating 'PLEASE REDUCE SPEED'	Low (\$500)	Outstanding
37057	Oxford Road 37	Trim the vegetation obstructing the warning system installed on the westbound approach	Low (\$500)	Complete
264210	Oxford Road 27	Relocate the STOP AHEAD sign obstructing the view within the stopping sight distance past the crossing	Low (\$500)	Complete
434801	Oxford Road 11	Prohibit on-street parking on the southeast corner of the crossing between Beachville Road and the railway corridor	Low (\$500)	Further review completed, determined there were no other parking options, hence parking is not prohibited

		Install 30 km/h 'Speed Advisory Tab' signs below the Railway Crossing Ahead signs	Low (\$500)	Complete
374622	Oxford Road 6	Install 30 km/h 'Speed Advisory Tab' signs below the existing Railway Crossing Ahead signs	Low (\$500)	Complete