Report No. PW 2023-17
Attachment 1

Speed & Road Safety Review Post Monitoring

Drumbo, Oxford Road 3 & Oxford Road 29 Plattsville, Oxford Road 8 (Albert Street) Bright, Oxford Road 8 & Oxford Road 22

Presentation to Township of Blandford-Blenheim Council February 15, 2023

Frank Gross, Oxford County Manager of Transportation and Waste Management Services



Drumbo Traffic Calming Implementations

Historical Findings (2019)


- Marginally excessive speeds at approaches
- Speeds within village not excessive

Traffic Calming Implementation Measures


- 60km/hr transition zone adjusted at south limit (July 2019)
- PXOs installed Oxford St at Matheson St & Mechanics St (2020)



Pre/Post Speed Data - OR 3



Pre/Post Speed Data - OR 29



Drumbo Post Monitoring Review Findings

- Excessive speeds at approaches incoming/outgoing
- Excessive speeds WB after all-way stop
- Excessive speeds through 40km/hr school zone on Wilmot St

 Speed transition zones at approaches are ineffective in reducing speeds



Posted Speed Limits – OR 3

SEGMENT	POSTED SPEED (KM/H)	TAC RECOMMENDED POSTED SPEED* (KM/H)	DIFFERENCE (KM/H)	OXFORD COUNTY RECOMMENDED POSTED SPEED (KM/H)
Twp Road 6 and 50m south of Maitland Street – Rural	60/80	80	+20/0	80
50m south of Maitland Street and Taylor Street – Urban	40/50	60	+20/+10	50
Taylor Street and Twp Road 8 – Rural	60/80	80	+20/0	80

^{*}TAC Canadian Guideline for Establishing Posted Speed Limits (2009)




Posted Speed Limits – OR 29

SEGMENT	POSTED SPEED (KM/H)	TAC RECOMMENDED POSTED SPEED* (KM/H)	DIFFERENCE (KM/H)	OXFORD COUNTY RECOMMENDED POSTED SPEED (KM/H)
Goble Road and 630m west of OR 3 – Rural	60/80	80	+20/0	80
630m west of OR 3 and 405m east of OR 3 – Urban	50	60	+10	50
405m east of OR 3 and Motheral Road – Rural	60/80	80	+20/0	80

^{*}TAC Canadian Guideline for Establishing Posted Speed Limits (2009)



Drumbo Recommendations – Immediate



Plattsville Traffic Calming Implementations

Historical Findings (2016)


Excessive speeds at east end

Traffic Calming Implementation Measures


- 10m raised centre island installed, east end (2016)
- Street lighting extended to illuminate traffic island (2016)



Plattsville Raised Centre Island



Pre/Post Speed Data



Plattsville Post Monitoring Review Findings

- Traffic island had minimal impact on reducing speeds
- Vehicles able to maintain speed through traffic island by encroaching bike lanes
- Excessive speeds in 50km/hr zone at east end



Posted Speed Limits - OR 8


SEGMENT	POSTED SPEED (KM/H)	TAC RECOMMENDED POSTED SPEED* (KM/H)	DIFFERENCE (KM/H)	OXFORD COUNTY RECOMMENDED POSTED SPEED (KM/H)
Douro Street and Hofstetter Road – Urban	50 ¹ /60	60	+10/0	50
Hofstetter Road and 350m east of OR 3 – Rural	80	80	0	80

¹ A "40 km/h when flashing" zone is present in this segment of OR 8 fronting Plattsville Christian School.



^{*}TAC Canadian Guideline for Establishing Posted Speed Limits (2009)

Plattsville Recommendations – Immediate



Bright Traffic Calming Implementations

Historical Findings


- Excessive speeds at east/west approaches
- Marginally excessive speeds at north/south approaches

July 2019

Adjusted speed zones on OR 8 to limits of built up areas



Pre/Post Speed Data



Bright Post Monitoring Review Findings

Excessive speeds at approaches

 Excessive speeds EB & WB after allway stop



Posted Speed Limits – OR 8

SEGMENT	POSTED SPEED (KM/H)	TAC RECOMMENDED POSTED SPEED* (KM/H)	DIFFERENCE (KM/H)	OXFORD COUNTY RECOMMENDED POSTED SPEED (KM/H)
215m west of Cuthbertson Street to 125m east of Hewitt Street – Urban	50/60	60	+10/+20	50

^{*}TAC Canadian Guideline for Establishing Posted Speed Limits (2009)




Posted Speed Limits – OR 22

SEGMENT	POSTED SPEED	TAC RECOMMENDED	DIFFERENCE (KM/H)	OXFORD COUNTY RECOMMENDED
	(KM/H)	POSTED SPEED* (KM/H)	(IXIVIII)	POSTED SPEED (KM/H)
865m south of OR 8 to 200m north of OR 8 – Urban	50	60	+10	50

^{*}TAC Canadian Guideline for Establishing Posted Speed Limits (2009)



Bright Recommendations – Immediate



Future Implementation Measures

- Physical features at village limits
 - Centre traffic island
 - Lateral lane shifts
 - Flexible centerline delineators
- Curb extensions (bump outs)
- Ongoing Police enforcement and speed data sharing
- Automated speed enforcement in school zones and CSZ



Next Steps

- Public Communication (mailouts)
- Report to County Council March 22, 2023
- Implementation of immediate measures
 - Speed zone adjustments
 - Installation of speed feedback signs
 - Addition of street lighting
 - Community Safety Zone implementation (where warranted)
- Post Monitoring



Speed & Road Safety Review Post Monitoring

THANK YOU

